



This version of the schematic has been corrected. The previous version (1.0) contained an error in the RS latch reset circuit: the wrong RST was connected to the latch RESET input. The issue was reported by Piwkooo/Atari.Area

Title Turbo HIT Cartridge		
Size A4	Number (rev. eng. from real hardware)	Revision 1.1
Date: 2026-03-19	Sheet 1 of 1	
File: F:\projects\...\turbo hit.SchDoc	Drawn By: Seban / Slight	